



## Meeting Agenda Screw Conveyor Training Workshop Bar Screens

**Date:** TBD **Project:** Spring Street STP Phase 1  
**Time:** 8:00 A.M. - 12:00P.M.  
**Location:** Spring Street STP, Klamath Falls, OR

---

### 1.1 Objective

The meeting objective is to present approaches and methodologies for operating, controlling and maintaining the Screening Conveyor at Spring Street STP. The Operation and Maintenance Manual to be used during classroom portion.

### 1.2 Meeting Plan

Time	Description
8:00 – 8:30 am	Conveyor Overview
8:30 – 9:30 am	Explain Conveyor Components
9:30 – 10:00 am	Overview of Maintenance
10:00 – 10:30	Break
10:30am – 12:00pm	In Field going over Conveyor components
12:00 - 12:10pm	Questions?

**Instructor Name: Conrad Davidson**